

KENCO ENGINEERING COMPANY

P.O. BOX 470426 TULSA, OK 74147-0426

PHONE: (918) 663-4406 FAX: (918) 663-4480

www.kenco-eng.com e-mail: info@kenco-eng.com

REPAIR KITS FOR MODEL 507 SERIES OIL CONTROLLERS

MODEL K507L & K507L-HP

RK-K507L

CONSISTS OF:

- (1) RETAINING RING
- (1) SCREEN
- (1) VALVE SEAT, BUNA-N
- (1) K507-L FLOAT ASSEMBLY
- (1) CLEVIS PIN
- (1) E-RING

MODEL K507L-V & K507L-V-HP

RK-K507L-V

CONSISTS OF:

- (1) RETAINING RING
- (1) SCREEN
- (1) VALVE SEAT, VITON
- (1) K507-L FLOAT ASSEMBLY
- (1) CLEVIS PIN
- (1) E-RING

MODEL K507L (ALL K507L'S)

MS-K507L (SWITCH KIT)

CONSISTS OF:

- (1) INSULATOR BUSHING
- (1) SET SCREW, SLOTTED CUP POINT, 10-32
- (1) STANDOFF
- (2) SETSCREW, SOCKET HEAD, 4-40 X 1/8"
- (1) WRENCH, .050" ALLEN

MODEL 507L & 507L-HP:
RK-507L

CONSISTS OF:

- (1) RETAINER RING
- (1) COTTER PIN
- (1) CLEVIS PIN
- (1) 507-L FLOAT ASSEMBLY
- (1) VALVE SEAT, BUNA-N
- (1) SCREEN

MODEL 507L-V & 507L-V-HP:
RK-507L-V

CONSISTS OF:

- (1) RETAINER RING
- (1) COTTER PIN (ZP)
- (1) CLEVIS PIN (ZP)
- (1) 507-L FLOAT ASSEMBLY
- (1) VALVE SEAT, VITON
- (1) SCREEN

MODEL 507M & 507M-HP:
RK-507M

CONSISTS OF:

- (1) FLOAT ASSEMBLY
- (1) SEAL, BUNA-N
- (1) CLEVIS PIN
- (1) COTTER PIN
- (1) GASKET
- (1) RETAINER RING
- (1) SCREEN

MODEL 507M-V & 507M-V-HP:
RK-507M-V

CONSISTS OF:

- (1) FLOAT ASSEMBLY
- (1) SEAL, VITON
- (1) CLEVIS PIN
- (1) COTTER PIN
- (1) GASKET
- (1) RETAINER RING
- (1) SCREEN

MODEL 507-K
GSK-507-K (GASKET KIT)

CONSISTS OF:

- (1) GASKET**
- (1) SCREEN**

RK-V-507-K (VALVE SEAT REPAIR KIT – MODELS MANUFACTURED AFTER 1984)

CONSISTS OF:

- (1) VALVE SEAT**
- (1) BALL**
- (1) O-RING**

RK-FL-507-K (FLOAT REPAIR KIT)

CONSISTS OF:

- (1) FLOAT ASSEMBLY**
- (1) NUT**
- (1) SCREW**
- (1) ROLL PIN**